INSPECTION REPORT

Partial Complete XXX Exploration Inspection Date: 06/10/2003 Time: 10:00am-2:00pm Date of Last Inspection: 05/08/2003

Mine Name: Emery Deep Mine County: Emery	Permit Number: <u>C/015/015</u>				
Permittee and/or Operator's Name: Consolidation Coal Company					
Business Address: P.O. Box 566, Sesser IL 62884/P.O. Box	=				
Company Official(s): Seth McCourt	•				
State Official(s): Stephen J. Demczak Federal Official(s): None					
Weather Conditions: Sunny, 80's					
Type of Mining Activity: Underground XXX Surface Programme Program	rep PlantOther				
Existing Acreage: Permitted 5180 Disturbed 247 Regraded Seeded					
Status: Active					

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	Ш	[X]	
2.	SIGNS AND MARKERS	[X]	\Box		\Box
3.	TOPSOIL	[X]	\Box	[X]	\Box
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	\Box	[X]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]	\Box	[X]	\Box
c.	OTHER SEDIMENT CONTROL MEASURES	[X]			
d.	WATER MONITORING	[X]	\Box	[X]	
e.	EFFLUENT LIMITATIONS	[X]	\Box	[X]	
5.	EXPLOSIVES	[X]			
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<u>[X]</u>	\Box	\Box	\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	\Box	\Box	\Box
8.	NONCOAL WASTE	[X]	\Box	$\overline{[X]}$	\Box
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES	[X]	\Box	\Box	\Box
10.	SLIDES AND OTHER DAMAGE	[X]	\Box	\Box	\Box
11.	CONTEMPORANEOUS RECLAMATION	[X]	\Box	\Box	\Box
12.	BACKFILLING AND GRADING	[X]	\Box	\Box	\Box
13.	REVEGETATION	[X] [X]	\Box	\Box	\Box
14.	SUBSIDENCE CONTROL	[X]	\Box	\Box	\Box
15.	CESSATION OF OPERATIONS	[X]		\Box	\Box
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[X]		\Box	\Box
b.	DRAINAGE CONTROLS	[X]		\Box	\Box
17.	OTHER TRANSPORTATION FACILITIES	[X]			
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	\Box	[X]	\Box
19.	AVS CHECK (4 th Quarter- April, May, June)	[X]			\Box
20.	AIR QUALITY PERMIT	[X]		\Box	\Box
21.	BONDING & INSURANCE	[X]	\Box	[X]	\Box

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/015/015</u> DATE OF INSPECTION: <u>06/10/2003</u>

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee has submitted an amendment to the Division to abate Notice of Violation N03-39-1-1. The amendment will extend the permit and the disturbed area to an additional 1.45 acres. It also gives detail on reducing the coal fines from leaving the permit area by constructing 20 ft. high silt fences, adding water sprays, scaling screen and bypass chute, and installing coal chute at the head roller. This amendment has been reviewed by the Division and has sent a TA adding several deficiencies with the amendment.

The permittee needs a current copy of the Mining and Reclaimation Permit. I advised the permittee to ask for a copy from the Division.

The permittee will need to update the SPCC plan. The plan has not been reviewed within the last three years. The permittee will most likely need to update the plan due to the new 4th East Portal facilities.

3. TOPSOIL

A small amount of vegetation has started to grow on the new topsoil pile at the Fourth East Portals.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot-checked and would function as designed.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The permittee has taken first quarter sediment pond inspection on March 14, 2003. No hazardous conditions were reported.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee has taken the fourth quarter water monitoring and submitted it into the EDS. The first quarter water data will be downloaded in the EDS by the end of the second quarter.

4E. HYDROLOGIC BALANCE: EFFLUENT LIMITATIONS

Discharge point 001 had exceeded total iron for one month in the first quarter. Restarting the water pump causes the increase in total iron after it has been idle for a period of time. Iron came from the pipe casing.

INSPECTION REPORT (Continuation Sheet)

PERMIT NUMBER: C/015/015 DATE OF INSPECTION:	00/10/2003	
8. NONCOAL WASTE		
The disturbed area was generally clear of non-coal waste material.		
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS		
The permittee has installed power poles along the fence line where coal fines are going permit area.	off the	
21. BONDING AND INSURANCE		
The insurance accord form was inspected and complies with the R645 Coal Rules. This expire on October 5, 2003.	s policy will	
Inspector's Signature:Date: June 19, 2003 Stephen J. Demczak #39		
Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, or	Gas & Mining.	
cc: James Fulton, OSM Tim Kirschbaum, Consol, Illinois, via email Seth McCourt, Consol, Emery, via email Price Field office O:\015015.EME\Compliance\2003\c_0610.doc		